## IN THE SPECIFICATION:

Please amend the paragraph on page 17, lines 19-23 of the Substitute Specification filed with the Response dated April 14, 2009, which corresponds to the paragraph on page 33, lines 2-6 of the originally filed Specification, as follows:

The peak 128a of the hub tooth section 128 has its <u>outside inside</u> radius  $\phi$ D3 remaining constant in the axial direction of the hub 114, and the valley 128b (FIGS. 17-18) of the hub tooth section 128 also has its inside radius  $\phi$ D4 remaining constant in the axial direction of the hub 114.